

CLAIM PROTOCOL

This claim protocol is necessary for settlement of a claim

Company: Veloplaneta Ltd

Address: 2E Yenakiyevskaya Str. , Khar-
kov 61158, UKRAINE

Responsible person: _____

Phone. Mob. _____

Date: 30,07,2013

Signature: _____

Town + country:				Don't fill in	
Pos.	Bike description	JOB	QC No.	Characterization of the problem	Technical expertise
1.	Bike 26" RockMachine TORRENT Disc grey, frame 16.5			Frame has a crack near the seattube	Unsuitably chosen frame height to the height of the customer. Seat is much too pulled.
2.					
3.					
4.					
5.					

YES ☐ NO ☐

Accepted claim parts send separately?

Issued by

Sopuch Lumír

Claim No.:

123/013

Seller stamp:

